

SENTEC Testing Laboratory Inc.

80 Esna Park Drive, Unit 25

Markham, ON L3R 2R6

Tel: (647) 495-8727; Cell: (416) 899-1882

E-mail: info@sentec.ca



An ISO 9001:2015 Certified Company

REPORT XYZ-005

ASSESSMENT OF A SILVER CONDUCTIVE EPOXY

Submitted to:

October 7th, 2018

This report is the subject of the following terms and conditions: 1. This report relates only to the specimen provided and there is no representation of warranty that it applies to similar substances of material or bulk the specimen is a part of. 2. The contents of this report is for the information of the customer identified above only and it shall not be reported or published in whole or in part without the prior written consent of SENTEC Testing Laboratory Inc. 3. The name SENTEC Testing Laboratory Inc. shall not be used in any connection with the specimen without the prior written consent of SENTEC Testing Laboratory Inc.. 4. Neither SENTEC Testing Laboratory Inc., nor any of its employees shall be responsible for any claims, loss or damages arising in consequences of reference to this report or any default, error or omission in its preparation or the tests conducted. 5. Specimens are retained for 2 months from the date of the test and then disposed unless instructed otherwise.

Background

A number of LED snow plow headlamps with heat grid exhibited a functionality issue. Due to the fact

that LEDs do not radiate heat, a heat grid has applied to the lens to melt snow build up during winter.

Conductive ink from Henkel EDAG 479SS E&C was used to print the heat grid on the B side of the

lens (reference attached drawing H4139-6).

A circuit board (heat grid controller) has attached to the lens to control power to the heat grid using

conductive epoxy from MG Chemical part # 8331S (reference attached drawing MG8331S). After

applying the conductive epoxy paste, the lenses with the heat grid controller were baked inside the oven

at +65C for 2 hrs.

The issue we are having is that the conductive epoxy which makes electrical contact between the

controller circuit and the heat grid on the lens has increased resistance. 8pcs out of 126pcs exhibited

failure. The resistance of the heat grid which is around 12ohms was measured over 50ohms at the

controller.

Therefore, a request was made to X-Ray the contact as shown below on two headlamps, as well as to

establish the degree of curing of the conductive epoxy.



X-Ray to find any voids



Test Procedure

The contact areas from two of the headlamps exhibiting the problem were inspected in an X-ray

machine. Upon completion of the inspection, a sample of the epoxy was collected from one of the lamps

and ran through a differential scanning calorimeter (DSC), in order to establish the degree of curing.

Glass transition temperature (T_g) was measured during a first and second heating of the epoxy and delta

T_g value (difference between the parameter measured during first and second heating) calculated.

Results and Discussion

Typical results of the analysis are shown in the Figures1 through 3 below. As can be seen from the results

of X-ray inspection of the areas of interest, no voiding but rather areas with different shades of grey were

observed in the conductive epoxy of both headlamps – Figs. 1 and 2. Brighter contrast areas indicate the

presence of fewer Ag particles, compared to the darker looking areas.

Cross-sectional SEM analysis of the areas might be beneficial in understanding the distribution of the

particles in the epoxy.


DSC analysis of the epoxy showed that it was properly cured as glass transition temperature (T_g) was


measured at 28⁰C during both cycles of heating - Fig 3.

Conclusion

Based on the findings it seems reasonable to conclude that additional tests would require to shed more light

on the root cause of the functional failure of the headlamps.





Brighter contrast - less dense areas (fewer Ag

Darker contrast - denser areas (more Ag particles)

Figure 1. Typical results of X-ray inspection of a fist headlamp (37.4 Ω).





Figure 2. Typical results of X-ray inspection of the second headlamp (300 Ω).




Figure 3. Typical results of the DSC test. The epoxy was cured properly.